

## Cross reference of Vacuum Measurements Boiling Temperatures of Water at Converted Pressures

Temp. F°	Microns	Inches of Hg Vacuum	Pressure Pounds Sq. In.
212	759,968	0.00	14.696
205	535,000	4.92	12.279
194	525,526	9.23	10.162
176	355,092	15.94	6.866
158	233,680	20.72	4.519
140	149,352	24.04	2.888
122	92,456	26.28	1.788
104	55,118	27.75	1.066
86	31,750	28.67	0.614
80	25,400	28.92	0.491
76	22,860	29.02	0.442
72	20,320	29.12	0.393
69	17,780	29.22	0.344
64	15,240	29.32	0.295
59	12,700	29.42	0.246
53	10,160	29.52	0.196
45	7,620	29.62	0.147
32	4,572	29.74	0.088
21	2,540	29.82	0.049
6	1,270	29.87	0.0245
-24	254	29.91	0.0049
-35	127	29.915	0.00245
-60	25.4	29.919	0.00049
-70	12.7	29.9195	0.00024
-90	2.5	29.9199	0.00005
	0.00	29.92	0.00000

JB Industries  
 Technical Support  
 800-323-0811  
[www.jbind.com](http://www.jbind.com)

Form 10710-308  
 © 2012 JB Industries



MADE IN THE USA