

<b>% Vacuum</b>	<b>Torr (mm Mercury)</b>	<b>Micron</b>	<b>psia, (lb/in<sup>2</sup> abs)</b>	<b>Inches Mercury Absolute</b>	<b>Inches Mercury Gauge</b>	<b>kPa abs</b>
0.0	760.0	760,000	14.7	29.92	0.00	101.4
1.3	750.0	750,000	14.5	29.5	0.42	99.9
1.9	735.6	735,600	14.2	28.9	1.02	97.7
7.9	700.0	700,000	13.5	27.6	2.32	93.5
21.0	600.0	600,000	11.6	23.6	6.32	79.9
34.0	500.0	500,000	9.7	19.7	10.22	66.7
47.0	400.0	400,000	7.7	15.7	14.22	53.2
50.0	380.0	380,000	7.3	15.0	14.92	50.8
61.0	300.0	300,000	5.8	11.8	18.12	40
74.0	200.0	200,000	3.9	7.85	22.07	26.6
87.0	100.0	100,000	1.93	3.94	25.98	13.3
88.0	90.0	90,000	1.74	3.54	26.38	12
89.5	80.0	80,000	1.55	3.15	26.77	10.7
90.8	70.0	70,000	1.35	2.76	27.16	9.3

<b>% Vacuum</b>	<b>Torr (mm Mercury)</b>	<b>Micron</b>	<b>psia, (lb/in<sup>2</sup> abs)</b>	<b>Inches Mercury Absolute</b>	<b>Inches Mercury Gauge</b>	<b>kPa abs</b>
92.1	60.0	60,000	1.16	2.36	27.56	8
93.0	51.7	51,700	1.00	2.03	27.89	6.9
93.5	50.0	50,000	0.97	1.97	27.95	6.7
94.8	40.0	40,000	0.77	1.57	28.35	5.3
96.1	30.0	30,000	0.58	1.18	28.74	4
96.6	25.4	25,400	0.49	1.00	28.92	3.4
97.4	20.0	20,000	0.39	0.785	29.14	2.7
98.7	10.0	10,000	0.193	0.394	29.53	1.3
99.0	7.6	7,600	0.147	0.299	29.62	1.0
99.87	1.0	1,000	0.01934	0.03937	29.88	0.13
99.90	0.75	750	0.0145	0.0295	29.89	0.1
99.99	0.10	100	0.00193	0.00394	29.916	0.013
99.999	0.01	10	0.000193	0.000394	29.9196	0.0013
100	0.00	0	0	0	29.92	0